

Test Verification of Conformity

Verification Number: 210902250SHA-V2

On the basis of the tests undertaken, the sample<s> of the below product have been found to comply with the requirements of the referenced specification<s>/standard<s> at the time the tests were carried out. This verification is part of the full test report<s> and should be read in conjunction with it <them>.

| | |
|---|---|
| Applicant Name & Address: | Pump Power Technology Co., Ltd. 519 TOWER A, RONGCHAOBINHAI BUILDING, HAIXIU ROAD 2021, BAOAN DISTRICT, SHENZHEN, CHINA |
| Product Description: | Utility-Interactive Micro Inverter |
| Ratings & Principle Characteristics: | See Appendix (Specifications table) |
| Models/Type References: | WVC-300/WVC-350/WVC-600/WVC-700/WVC-1200/WVC-1400/WVC-1600/WVC-2000 |
| Brand Name: | PUMPOWER |
| Relevant Standards: | DIN V VDE V 0126-1-1: 2013 |
| Verification Issuing Office Name & Address: | Intertek Testing Services Shanghai Building No.86, 1198 Qinzhou Road (North), Shanghai 200233, China |
| Date of Tests: | 2021-06-22 to 2021-08-17 |
| Test Report Number(s): | 210902250SHA-002 |

Additional information in Appendix.

Signature



Name: Jonny Jing
Position: Manager
Date: 2021-09-29

This Verification is for the exclusive use of Intertek's client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Verification. Only the Client is authorized to permit copying or distribution of this Verification. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test/inspection results referenced in this Verification are relevant only to the sample tested/inspected. This Verification by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.